

Assembly Instructions

PARTS LIST

Model No.: H1(3)48R-RTA


8	6 PCS	Machine Bolts (1-1/4")			Metal Grommet			
∞	2 PCS	Keys For File Drawer Lock		2 PCS	Long(1-1/4") Flat Head Wood Screws			
0	4 PCS	Wood Dowels (\$\phi 8x25mm)	8	2 PCS	Tambour Keys			
	8 PCS Short (3/4") Flat Head Wood Screws							

PARTS LIST										
PACKAGE NO.	PART NO.	DESCRIPTION	QTY	PART NO.	DESCRIPTION	QTY				
	A	PEDESTAL	1 PC	D	CROSS BAR	1 PC				
H148R H348R	В	PEDESTAL	1 PC	E	DESK TOP	1 PC				
	C	BACKPANEL	1 PC	F	DROP FRONT CENTER DRAWER	1 PC				

Notes: Need two people to assemble.

Instructions:

- ① Move the pedestals ② B to the desired location, insert and tighten machine Bolts(1-1/4")(6 PCS) to connect backpanel C to the two pedestals.
- 2) Insert center Cross Bar (D), tighten long(1-1/4") flat head wood screws(2 PCS).




WINES

Assembly Instructions


Model No.: H1(3)48R-RTA

3) Insert two wood dowels (4 PCS) in each pedestal (A) (B).

4) Loosen the screw to adjust metal figure 8 (8 PCS) of its direction of the panel.




(5) Insert short (3/4") flat head wood screws (8 PCS) through metal figure 8 to connect Desk top (2) and pedestals.



Assembly Instructions

(6) Install the Drop Front center Drawer (F) to place . Important:

(Be sure to move the ball bearing retainer all the way to the front of the glide and carefully slide the rails into the glides and ball bearing retainer.)





Assembly is now complete.

Model No.: H1(3)48R-RTA